

- A. Model 35/40 and 50 Manual Rewind Starter Assemblies
- B. Fuel Pump Diaphragm Gasket Kit, Part No. 27-75360A1

CIRCULATE TO:  
SERVICE MANAGER   
PARTS MANAGER   
MECHANICS   
"Place in a Service  
Bulletin Binder"

**A. MODELS 35/40 and 50 MANUAL REWIND STARTER ASSEMBLIES**

Model 35/40 starter rewind housing, Part No. 76080A1 can no longer be obtained and therefore, has been superseded to starter rewind assembly complete, Part No. 76079A8.

Model 50 starter rewind housing, Part No. 89930 can also no longer be obtained and therefore, has been superseded to starter rewind assembly complete, Part No. 89016A3.

Starter rewind assemblies, 76079A8 and 89016A3 are complete and consist of the latest revisions of starter housing, sheave plate, rewind spring, rope etc.

50-94338A1, starter sheave and 91936, starter pawl used on the 35/40 and 50 are no longer available. For replacement, the complete starter rewind assembly must be ordered depending on engine model, 76079A8 for the 35/40 or 89016A3 for the 50.