


Testing ECT sensor

BF200A•225A

e. ECT SENSOR

- MIL blinks 6 times with service check connector shorted (P. 5-14).



To P. 5-32