

SE106 TRIM CYLINDERS

#9B-102-01 REPLACES OE #87173A-5 (CYLINDERS ARE PERFECTLY ROUND)

9B-102-01 link



FITS '70-'82 STYLE DRIVES NOTE:

IF BOTH HOSES AT ONE END AND HAS MANIFOLD BOX ON BACK OF BOAT (under gimbal housing) WHERE ALL 4 HOSES GO INTO—MUST BUY HOSE KIT FOR OUR CYLINDERS TO WORK.

NO MANIFOLD BOX—OUR CYLINDERS WILL NO WORK

#9B-104-01/02 REPLACES OE #98703A4 / #98704A3

9B-104-01 link

9B-104-02 link



15-1/2"

= 15 1/2"

#9B-106-01/02 REPLACES OE #14034A3 / #14035A3

9B-106-01 link

9B-106-02 link



16-3/16"

= 16 3/16"

shell
Inlet = flat