





These armature plate assemblies service all 4 Deluxe thru 60 models, 1977 to date, with C.D. II ignition.

(1)(2) The armature plate assembly has a lead cover A WITHOUT stop. Included with assembly is lead cover B with stop. If the model you are servicing requires a lead cover WITH a stop, remove and discard lead cover WITHOUT stop and install lead cover WITH stop. Refer to service manual for installation instructions.