



# STATOR ASSEMBLY P/N 582097 REPLACES 581387 AND 581252 STATOR ASSEMBLIES

### Installation Instructions

#### **PREFACE**

Printed in the United States.

This stator will be used for service on all Johnson® and Evinrude® 9.9 through 40 HP models, 1974 thru 1976.

Follow instructions in your service manual for proper assembly.

After assembly is complete, you will find on some models the leads to terminal block are too long. Coil the excess wire up and tape neatly. Do this near the terminal block where it will not interfere with moving parts.



©2004 BRP US Inc. All rights reserved. TM, ® Trademarks and registered trademarks of Bombardier Recreational Products Inc. or its affiliates.





## STATOR ASSEMBLY P/N 582097 REPLACES 581387 AND 581252 STATOR ASSEMBLIES

### **Installation Instructions**

#### **PREFACE**

This stator will be used for service on all Johnson® and Evinrude® 9.9 through 40 HP models, 1974 thru 1976.

Follow instructions in your service manual for proper assembly.

After assembly is complete, you will find on some models the leads to terminal block are too long. Coil the excess wire up and tape neatly. Do this near the terminal block where it will not interfere with moving parts.

