

■ The engine coupler should be well lubricated annually or whenever the out drive is removed for service.

We recommend the drive shaft splines be lubricated with Sierra Spline Grease part # 18-9200 (replaces Mercury 92—816391A4).

Sierra Spline Grease is specially formulated for extreme pressure applications and helps prevent wear and premature failure of the drive shaft splines. The use of a multi-purpose grease may result in premature failure of the system.

N-1467