

NOTICE

When replacing the OE Mercury voltage regulator with the Sierra version 18-5743/18-5744, you will note that the Sierra version has no “ground” lead to attach like the OE. The Sierra version grounds through the case once secured and no additional grounding leads are required. These regulators have internal capacitors to protect against high voltage spike, allowing the replacement of both OE regulators.