




Everything feels secure...

Noticed This!




Bought a new pulley, bushing, and bolt just in case.

Noticed these two brackets were reversed. I flipped them from this picture.



I wonder if I have the wrong alternator?



But then, that created a gap here...
Between the alternator bracket and the
idler bracket. A gap of about 19mm.