

March 31, 1958

#510354 Bumper Band cancelled and superseded by #203290 Bumper Head -
Magneto Assembly Number




Figure 1

Bumper Band #510354 formerly located at position "A" of the magneto assembly has been cancelled and replaced by bumper head - shown at position "B" - Figure 1.

To make the modified replacement, drill a 1/4" hole 1-3/16" deep in the magneto mounting bracket as shown Figure 2.





Figure 2

#510395